

# ES\_LPC5411x

Errata sheet LPC5411x

Rev. 1.5 — 4 August 2017

Errata sheet

## Document information

Info	Content
<b>Keywords</b>	LPC54113J256UK49, LPC54114J256UK49, LPC54113J128BD64, LPC54113J256BD64, LPC54114J256BD64
<b>Abstract</b>	LPC5411x errata



## Revision history

Rev	Date	Description
1.5	20170804	<ul style="list-style-type: none"> <li>Added USB ROM.1.</li> </ul>
1.4	20170505	<ul style="list-style-type: none"> <li>Updated <a href="#">Table 2 “ Functional problems table”</a>: changed heading row to Functional problems.</li> </ul>
1.3	20170421	<ul style="list-style-type: none"> <li>Added CRP.1</li> <li>Removed IAP.1. IAP call is functional. Use the procedure described in the LPC5411x user manual.</li> </ul>
1.2	20161014	<ul style="list-style-type: none"> <li>Added I<sup>2</sup>S.3.</li> <li>Added I<sup>2</sup>C.1.</li> <li>Added USART.1.</li> <li>Added USART.1.</li> </ul>
1.1	20160222	<ul style="list-style-type: none"> <li>Added USB.1.</li> <li>Added I<sup>2</sup>S.1.</li> <li>Added I<sup>2</sup>S.2.</li> <li>Removed deep-sleep2 from <a href="#">Section 3.3 “ADC.1: High current consumption in reduced low power modes when using ADC.”</a></li> </ul>
1	20160216	<ul style="list-style-type: none"> <li>Initial version</li> </ul>

## Contact information

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

## 1. Product identification

The ES\_LPC5411x LQFP64 package has the following top-side marking:

- First line: LPC5411xJyyy
  - x: 4 = dual core (M4, M0+), 1, 3 = single core (M4)
  - yyy: flash size
- Second line: BD64
- Third line: xxxxxxxxxxxx
- Fourth line: xxxyywwx[R]x
  - yyww: Date code with yy = year and ww = week.
  - R = Chip revision.

The ES\_LPC5411x WLCSP49 package has the following top-side marking:

- First line: LPC5411x
  - x: 4 = dual core (M4, M0+), 1, 3 = single core (M4)
- Second line: JxxxUK49
  - xxx: flash size
- Third line: xxxxxxxx
- Fourth line: xxxyyww
  - yyww: Date code with yy = year and ww = week.
- Fifth line: xxxxx
- Sixth line: NXP x[R]x
  - R = Chip revision.

**Table 1. Device revision table**

Revision identifier (R)	Revision description
'A'	Initial device revision

## 2. Errata overview

**Table 2. Functional problems table**

Functional problems	Short description	Revision identifier	Detailed description
ISP.1	ISP (In-System Programming) command for UID (unique identification number) is not functional.	'A'	<a href="#">Section 3.1</a>
ISP.2	ISP 'Z' command is not reliable for flash signature generation.	'A'	<a href="#">Section 3.2</a>
ADC.1	High current consumption in reduced low power modes when using ADC.	'A'	<a href="#">Section 3.3</a>
USB.1	Automatic USB rate adjustment not functional when using multiple hubs.	'A'	<a href="#">Section 3.4</a>
I <sup>2</sup> S.1	FIFO underflow interrupt not generated for I <sup>2</sup> S peripheral.	'A'	<a href="#">Section 3.5</a>
I <sup>2</sup> S.2	The Most Significant Bit (MSB) of I <sup>2</sup> S receive data is forced to 0 if DATALEN is greater than 23.	'A'	<a href="#">Section 3.6</a>
I <sup>2</sup> S.3	Incorrect synchronization to the second edge of the WS instead of the start of frame.	'A'	<a href="#">Section 3.7</a>
I <sup>2</sup> C.1	The AUTOACK feature does not work reliably when the CPU system clock frequency is three times or more than the peripheral clock to the I <sup>2</sup> C interface.	'A'	<a href="#">Section 3.8</a>
USART.1	The USART receiver timeout feature is not supported.	'A'	<a href="#">Section 3.9</a>
USART.2	The USART receiver idle (RXIDLE) interrupt feature is not supported.	'A'	<a href="#">Section 3.10</a>
CRP.1	Code read protection level 1 is not functional.	'A'	<a href="#">Section 3.11</a>
USB_ROM.1	FRAME_INT is cleared if new SetConfiguration or USB_RESET are received.	'A'	<a href="#">Section 3.12</a>

**Table 3. AC/DC deviations table**

AC/DC deviations	Short description	Revision identifier	Detailed description
n/a	n/a	n/a	n/a

**Table 4. Errata notes**

Note	Short description	Revision identifier	Detailed description
n/a	n/a	n/a	n/a

### 3. Functional problems detail

---

#### 3.1 ISP.1: ISP (In-System Programming) command for UID (unique identification number) is not functional.

**Introduction:**

Each LPC5411x device contains a device serial number (four 32-bit words) for unique identification. The ISP call (ReadUID) can be performed via the USART interface to read the unique serial number where the word at the lowest address is sent first.

**Problem:**

On the LPC5411x, the read UID ISP command is not functional.

**Work-around:**

The unique serial number (four 32-bit words) can be directly read from address locations 0x0100 0100 to 0x0100 010C.

### 3.2 ISP.2: ISP 'Z' command is not reliable for flash signature generation

**Introduction:**

On the LPC5411x devices, the ISP 'Z' command is used to determine the signature of the entire flash memory using an internal flash signature generator.

**Problem:**

The ISP 'Z' command is not reliable on the LPC5411x devices. In most cases, the signature will be correct but due to a signature generation timing sensitivity, the result may be incorrect and therefore unreliable.

**Work-around:**

Use the flash signature generation registers documented in the LPC5411x User Manual to create the signature of the entire flash memory.

### 3.3 ADC.1: High current consumption in reduced low power modes when using ADC.

#### Introduction:

The 12-bit ADC controller is available on all LPC5411x parts. The ADC can measure the voltage on any of the input signals on the analog input channel. For accurate voltage readings, the digital pin function on the ADC input channel must be disabled by writing a 0 to the DIGIMODE bit in the related IOCON register. This enables the analog mode functionality on the ADC input channel.

#### Problem:

For applications using the ADC, the current consumption could be higher than expected in reduced power modes (deep-sleep and deep power-down modes) or when the ADC is disabled using the PDRUNCFG register.

#### Work-around:

To prevent high current consumption, use the following steps in the software:

1. Following a chip reset, all 12 ADC input channels (ADC0\_0 to ADC0\_11) should be in Digital Mode (DIGIMODE = 1) in the related IOCON registers until the configuration of the ADC block is complete. See the Basic Configuration section in the LPC5411x 12-bit ADC controller (ADC) chapter of the LPC5411x User Manual
2. After configuring the ADC, change only those pins that are used as ADC input channels to Analog Mode (DIGIMODE = 0) in the related IOCON registers before starting ADC conversions.
3. Before entering any reduced power mode (deep-sleep and deep power-down) or before powering down the ADC block (by writing to the PDEN\_ADC0 bit in the PDRUNCFG register), the ADC input channel(s) must be changed back to Digital Mode.
4. After waking up from the reduced power mode or when re-enabling the ADC block (PDEN\_ADC0 bit in the PDRUNCFG), the software must follow step 2 before starting ADC conversions.

### 3.4 USB.1: Automatic USB rate adjustment is not functional when using multiple hubs

#### Introduction:

Full-speed and low-speed signaling uses bit stuffing throughout the packet without exception. If the receiver sees seven consecutive ones anywhere in the packet, then a bit stuffing error has occurred, and the packet should be ignored.

The time interval just before an End of Packet (EOP) is a special case. The last data bit before the EOP can become stretched by hub switching skews. This is known as dribble and can lead to a situation where dribble introduces a sixth bit that does not require a bit stuff. Therefore, the receiver must accept a packet where there are up to six full bit times at the port with no transitions prior to the EOP.

#### Problem:

LPC5411x devices use the start of an EOP for frequency measurements. This is not functional when going through multiple hubs that introduce a dribble bit because of hub switching skews. For this reason, the start of the EOP cannot be used for frequency measurements for automatic USB rate adjustment (by setting USBCLKADJ in FROCTRL register). The problem does not occur when a single hub is used.

#### Work-around:

There is no work-around.



### 3.5 I2S.1: FIFO underflow interrupt not generated for I<sup>2</sup>S peripheral

#### Introduction:

Multiple Flexcomm Interfaces are available in the LPC5411x devices. Flexcomm Interface 6 and Flexcomm Interface 7 can be configured for I<sup>2</sup>S peripheral function and the data for all I<sup>2</sup>S traffic within one Flexcomm Interface uses the Flexcomm Interface FIFO. During I<sup>2</sup>S data transfers, when the transmit FIFO is empty, a FIFO underflow occurs and an interrupt is generated, which is flagged by the UNDERRUN bit in the I<sup>2</sup>S FIFOSTAT register.

#### Problem:

When the FIFO underflow condition occurs, the interrupt from the I<sup>2</sup>S peripheral function might not be generated and as a result, the UNDERRUN bit does not get set. This issue does not affect the SPI and USART peripherals.

#### Work-around:

There is no work-around.

### 3.6 I<sup>2</sup>S.1: The Most Significant Bit (MSB) of I<sup>2</sup>S receive data is forced to zero if DATALEN > 23

#### Introduction:

On the LPC5411x devices, the I<sup>2</sup>S function is included in Flexcomm Interface 6 and Flexcomm Interface 7. Each of these Flexcomm Interfaces implements one I<sup>2</sup>S channel pair. The Data Length (DATALEN) defines the number of data bits to be transmitted or received for all I<sup>2</sup>S channel pairs.

#### Problem:

If the I<sup>2</sup>S interface is configured for DATALEN (in I<sup>2</sup>S CFG1 register) greater than 23 (25-bit data or greater), the MSB of any received data will be forced to 0. If DATALEN = 24 (25-bit data), bit 24 of received data will always be 0. If DATALEN = 31 (32-bit data), bit 31 of received data will always be 0. The issue occurs regardless of the I<sup>2</sup>S operating mode (selected by MODE bits).

#### Work-around:

There is no work-around.

### 3.7 I<sup>2</sup>S.3: Incorrect synchronization to the second edge of the Word Select (WS) signal instead of the start of frame.

#### Introduction:

Multiple Flexcomm Interfaces are available in the LPC5411x devices. Flexcomm Interface 6 and Flexcomm Interface 7 can be configured for I<sup>2</sup>S peripheral function. The Word Select (WS) pin is the synchronizing signal for the beginning of each data frame and in some modes, left versus right channel data. It is normally driven by the master and received by one or more slaves.

#### Problem:

When I<sup>2</sup>S receives the WS signal from another master, that is, if MSTSLVCFG = 0x1 (WS Synchronized master) or 0x0 (Normal Slave mode) in the CFG1 register, and the I<sup>2</sup>S bus is already running, it can incorrectly synchronize to the second edge of the WS instead of the start of frame. This does not happen when the slave is started before the WS master.

#### Work-around:

The work-around is to detect the trailing edge on the WS pin and then enable the I<sup>2</sup>S interface. This can be achieved by using a rising or falling edge interrupt on a pin. The edge is determined by the starting mode of the WS pin. In I<sup>2</sup>S mode, the rising edge interrupt can be used so that the data frame starts from the falling edge. In DSP mode, the falling edge interrupt can be used so that the data frame starts from the rising edge.

### 3.8 I<sup>2</sup>C.1

**Introduction:**

In LPC5411x devices, the I<sup>2</sup>C interface has an AUTOACK bit in the Slave Control register. In the slave mode, when this bit is set, it will cause an I<sup>2</sup>C header, which matches the slave address SLVADR0 and the direction set by the AUTOMATCHREAD to be ACKed immediately. This is used with the DMA to allow processing of the data without intervention.

**Problem:**

The AUTOACK feature does not work reliably when the CPU system clock frequency is three times or more than the peripheral clock to the I<sup>2</sup>C interface.

**Work-around:**

The I<sup>2</sup>C peripheral clock frequency should be the same or half of the CPU system clock.

### 3.9 USART.1

**Introduction:**

A receiver timeout feature for the USART provides a means to get data left for a time in a FIFO that has not reached its threshold to be transferred. This feature exists in LPC5410x devices.

**Problem:**

The LPC5411x devices do not support the USART receiver timeout feature.

**Work-around:**

Timer0 can be used as a USART RX timeout timer and Flexcomm0 as USART0 peripheral in loop back mode. See the technical note TN00013 for more details.

### 3.10 USART.2

**Introduction:**

In the USART peripheral, the receiver idle (RXIDLE) interrupt occurs when the RX channel becomes idle. This feature exists in LPC5410x devices.

**Problem:**

The LPC5411x devices do not support the USART receiver idle (RXIDLE) interrupt feature.

**Work-around:**

There is no work-around.

### 3.11 CRP.1: Code read protection level 1 is not functional

#### Introduction:

Code Read Protection is a mechanism that allows the user to enable different levels of security in the system so that access to the on-chip flash and use of the ISP can be restricted. When needed, CRP is invoked by programming a specific pattern in the flash image at offset 0x0000 02FC. There are three levels of code read protection available to the user.

For CRP1 level, erase page command can erase pages in sector 0 only when all pages in the user flash are selected for erase.

#### Problem:

All pages in sector 0 except page 0 can be erased, which results in erasing CRP1 level.

#### Work-around:

Use CRP2 level or CRP3 level for code read protection.

### 3.12 USB\_ROM.1: FRAME\_INT is cleared if new SetConfiguration or USB\_RESET are received.

#### Introduction:

In the USB ROM API, the function call EnableEvent can be used to enable and disable FRAME\_INT.

#### Problem:

When the FRAME\_INT is enabled through the USB ROM API call:

```
ErrorCode_t(* USBD_HW_API::EnableEvent)(USB_HANDLE_T hUsb, uint32_t EPNum, uint32_t
    event_type, uint32_t enable),
```

the FRAME\_INT is cleared if new SetConfiguration or USB\_RESET are received.

#### Work-around:

Implement the following software work-around in the ISR to ensure that the FRAME\_INT is enabled:

```
void USB_IRQHandler(void)
{
    USBD_API->hw->EnableEvent(g_hUsb, 0, USB_EVT_SOF, 1);
    USBD_API->hw->ISR(g_hUsb);
}
```



#### **4. AC/DC deviations detail**

---

No known errata.

#### **5. Errata notes**

---

No known errata.

## 6. Legal information

### 6.1 Definitions

**Draft** — The document is a draft version only. The content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included herein and shall have no liability for the consequences of use of such information.

### 6.2 Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the *Terms and conditions of commercial sale* of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Suitability for use** — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or

malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors accepts no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from national authorities.

### 6.3 Trademarks

Notice: All referenced brands, product names, service names and trademarks are the property of their respective owners.

## 7. Contents

<b>1</b>	<b>Product identification</b> .....	<b>3</b>
<b>2</b>	<b>Errata overview</b> .....	<b>4</b>
<b>3</b>	<b>Functional problems detail</b> .....	<b>5</b>
3.1	ISP.1: ISP (In-System Programming) command for UID (unique identification number) is not functional. ....	5
3.2	ISP.2: ISP 'Z' command is not reliable for flash signature generation. ....	6
3.3	ADC.1: High current consumption in reduced low power modes when using ADC. ....	7
3.4	USB.1: Automatic USB rate adjustment is not functional when using multiple hubs. ....	8
3.5	I2S.1: FIFO underflow interrupt not generated for I2S peripheral .....	9
3.6	I2S.1: The Most Significant Bit (MSB) of I2S receive data is forced to zero if DATALEN > 23 ..	10
3.7	I2S.3: Incorrect synchronization to the second edge of the Word Select (WS) signal instead of the start of frame. ....	11
3.8	I2C.1 .....	12
3.9	USART.1 .....	13
3.10	USART.2 .....	14
3.11	CRP.1: Code read protection level 1 is not functional .....	15
3.12	USB_ROM.1: FRAME_INT is cleared if new SetConfiguration or USB_RESET are received..	16
<b>4</b>	<b>AC/DC deviations detail</b> .....	<b>17</b>
<b>5</b>	<b>Errata notes</b> .....	<b>17</b>
<b>6</b>	<b>Legal information</b> .....	<b>18</b>
6.1	Definitions .....	18
6.2	Disclaimers .....	18
6.3	Trademarks .....	18
<b>7</b>	<b>Contents</b> .....	<b>19</b>

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

© NXP B.V. 2017.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: 4 August 2017

Document identifier: ES\_LPC5411X