

Product Change Notification - SYST-13FBCD608

Date: 14 Feb 2020 Product Category: Wireless Modules Affected CPNs: ☑

Mification subject: Data Sheet - ATA5577C - Complete Datasheet Notification text: SYST-13FBCD608 Microchip has released a new Product Documents for the ATA5577C - Complete Datasheet of devices. If you are using one of these devices please read the document located at ATA5577C - Complete Datasheet.

Notification Status: Final

Description of Change:

8.2 Ordering Details for Pad Type 2 was updated
 Added new delivery option, "ATA5577M233TC-DBB"

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 14 Feb 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

ATA5577C - Complete Datasheet

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section. If you wish to <u>change your PCN profile</u>, including opt out, please go to the <u>PCN home page</u> select



login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATA5577M1330C-DDB ATA5577M1330C-DDW ATA5577M1330C-PAE ATA5577M1330C-PP ATA5577M1330C-PPMY ATA5577M1330C-UFQW ATA5577M133DC-DDB ATA5577M133DC-UFQW ATA5577M133DC-UGQW ATA5577M133SC-DDB ATA5577M2250C-DBB ATA5577M2330C-DBB ATA5577M2330C-DBQ ATA5577M233AC-DBB ATA5577M233SC-DBB ATA5577M233SC-DBQ ATA5577M233TC-DBB ATA5577M3330C-DBB ATA5577M3330C-DBQ ATA5577M3330C-DDB ATA5577M3330C-DDW ATA5577M3330C-DUQW ATA5577M3331C-DBB